

MISEQ FGX CONTROL SOFTWARE V1.4.7117.18976 RELEASE NOTES

MiSeq FGx Recipes v1.3.0.0

Real-Time Analysis (RTA) v1.18.54

MiSeq Reporter v2.5.1.3

BaseSpace Broker v2.9.2.15

ForenSeq Universal Analysis Software Service Broker
v1.3.6744.27820

Nexus Broker v1.8.0.0

Table of Contents

Introduction	2
MiSeq FGx Control Software v1.4.7117.18976	2
<i>New Features</i>	2
<i>Defect Repairs</i>	2
<i>Known Defects</i>	2
<i>Additional Notes.....</i>	3
Version History	3

Introduction

These release notes describe changes to components of the MiSeq FGx® Control Software v1.4.7117.18976 and known issues. If you are updating from a version prior to v1.4.7117.18976, review the release notes for v1.3.6744.33558 for information on the changes introduced in that release. See the applicable guides for instructions on using the software.

MiSeq FGx Control Software v1.4.7117.18976

The MiSeq FGx Control Software v1.4.7117.18976 includes the following software components and versions:

- MiSeq FGx Recipes v1.3.0.0
- Real-Time Analysis (RTA) v1.18.54
- MiSeq Reporter v2.5.1.3
- BaseSpace Broker v2.9.2.15
- ForenSeq™ Universal Analysis Software Service Broker v1.3.6744.27820
- Nexus Broker v1.8.0.0

New Features

- The Nexus service broker was implemented to communicate between the BaseSpace broker and the ForenSeq Universal Analysis Software v2.0 server.
- The login screen was modified to display an option for connecting to the ForenSeq Universal Analysis Software v2.0 server.

Defect Repairs

- Fixed an issue with an intermittent T-channel corruption that resulted in no signal.

Known Defects

- None

Additional Notes

- None

Version History

Version	Date	Description of Change
A	August 2020	Initial release