

MISEQ FGX CONTROL SOFTWARE V1.3.6744.33558 RELEASE NOTES

MiSeq FGx Recipes v1.3.0.0

Real-Time Analysis (RTA) v1.18.54

MiSeq Reporter v2.5.1.3

BaseSpace Broker v2.9.2.15

ForenSeq Universal Analysis Software Service Broker
v1.3.6744.27820

Table of Contents

Introduction	2
MiSeq FGx Control Software v1.3.6744.33558	2
<i>New Features</i>	2
<i>Defect Repairs</i>	2
<i>Known Defects</i>	2
<i>Additional Notes.....</i>	2
Version History	3

Introduction

These release notes describe changes to components of the MiSeq FGx® Control Software v1.3.6744.33558 and known issues. If you are updating from a version prior to v1.3.6744.33558, review the release notes for v1.3 for information on the changes introduced in that release. See the applicable guides for instructions on using the software.

MiSeq FGx Control Software v1.3.6744.33558

The MiSeq FGx Control Software v1.3.6744.33558 includes the following software components and versions:

- MiSeq FGx Recipes v1.3.0.0
- Real-Time Analysis (RTA) v1.18.54
- MiSeq Reporter v2.5.1.3
- BaseSpace Broker v2.9.2.15
- ForenSeq™ Universal Analysis Software Service Broker v1.3.6744.27820

New Features

- None

Defect Repairs

- The kit version is correctly set when the RFID for a run is read incorrectly.
- The post-run wash language was modified to: Preparing for the Post-Run wash.

Known Defects

- None

Additional Notes

- None

Version History

Version	Date	Description of Change
A	August 2020	Initial release